

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	General Information		
	1.	Report Time Period: From (mo./yr.) 11 03 To (mo./yr.) 12 03	
	2.	DOGM File Number (Mine No): 5 /023/065	
	3.	Mine Name: Keystone Quarry	
	4.	Mineral(s) Mined (or permitted to mine): Quay + 51+C	
	5.	Type of mine Surface Mine or Underground Mine	
	6.	Legal Description (Location of Lands Affected):	
		W 1/2, 5W 1/4, NE 1/4, Section 13, Township 105, Range 3W	
		W 1/2, NW 1/4, 5€ 1/4, Section 13, Township 105, Range 3W	
		5 1/2, NW 1/4, 5W 1/4, Section 25, Township 105, Range 3W	
7.	Name of Operator or Company: Anderson Engineering Company, Inc.		
	8.	Permanent Street Address: 977 W. 2100 5.	
		City, State, Zip: SLC, UT 84119	
		Phone: (801) 972.6222 Fax: (801) 972.6235	
	9.	Company Representative (or designated operator):	
		Name: Steven D. Anderson	
		Title: President	
		Business Address: 917 W. 2100 5.	
		City, State, Zip: SLC, UT 84119	
		Phone: (801) 972. 6222 Fax: (801) 972.6235	
		Please check if any of the above information has changed since previous year.	
I.	Minin	ng and Reclamation	
	1.	Was there any mine related activity during the past year? Yes ☑ No ☐	
	2.	If no - what was the last year of activity?	
	3.	If yes - how much ore or mineral was mined? None (Investigation only)	

RECEIVED

JAN 1 5 2004

-	Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.
	Backhoe - Dozer operations to define
	rock under shallow overburden.
	How much additional acreage was disturbed during the past year? 500 50. ft.
•	How much acreage was reclaimed during the past year? None
	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
8	What is the total disturbed acreage of entire project at years end? 500 sq. ft.
ç	Briefly summarize any mining and/or reclamation plans for the upcoming year. Reclaim area disturbed, or begin guarry operation Investigation currently underway to identify alternative sources.
NOTE:	Section III., "Additional Information" applies only to <u>large mining operations</u> .
III. Addit	nal Information - R647-4-121.2 and .3
1	The operator shall include an updated map depicting surface disturbance and reclamation performed during the year, prepared in accordance with Rule R647-4-105.
2.	The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.
IV. Signa	re Requirement
I	reby certify that the foregoing is true and correct.
	Name (Typed or Print): Steve D. Anderson
	Title of Operator: President
	Signature of Operator:
	Date: 12 Jan 104
jb	그래 그는 내용하는 하는 그는 그들은 것이 되었다. 그는 그를 가는 그를 가장하는 것이 없다.

o:\forms\reports\MR-AR